



# FACILITY COMPLIANCE INSPECTION REPORT

## Division of Waste Management Solid Waste Section

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY:</b> Robeson <b>PERMIT NO.:</b> SLAS 78-17 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** 4/17/2014

**Date of Last Inspection:** 10/22/2013

**FACILITY NAME AND ADDRESS:**

Little Chief Commercial Vacuum Pumping  
 P.O. Box 717  
 Maxton, NC 28364

**GPS COORDINATES:** N: 34.74481 E: -79.32706

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Eugene Locklear  
 Telephone: (910) 844-5855  
 Email address: ohcaroll@msn  
 Fax: (910) 844-8573

**FACILITY CONTACT ADDRESS:**

219 Buffalo Road  
 Maxton, NC 28364

**PARTICIPANTS:**

Connie Wylie

**STATUS OF PERMIT:**

Active – permit expires June 1, 2015

**PURPOSE OF SITE VISIT:**

Routine

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. The required signs are posted and the access road is adequate.
2. It appears that the approved setbacks are being met. Field markers appear accurate.
3. No sign of recent activity. No odors noted.
4. No sign of land application outside the permitted boundaries.
5. Please remove the tree/vegetation that is growing up around the marker at the back of field 1, left hand side.
6. Weed control is needed in the coming months.

Please contact me if you have any questions or concerns regarding this inspection report.



Connie S. Wylie  
***Regional Representative***

Phone: (910) 433-3352

Sent on:		Email		Hand delivery	<b>X</b>	US Mail		Certified No. <u>  </u>
----------	--	-------	--	---------------	----------	---------	--	-------------------------